

SAFETY UPGRADE NOTICE

This Notice applies to EAA Witness style semi-automatic pistols bearing serial numbers between AE00000 to AE70000. *It is important to note, this does not apply to firearms with serial numbers beginning with EA.*

EXAMPLE: *EA12345 is not included in the safety upgrade, whereas AE12345 is included.*

Any pistols bearing a serial number in this range should receive a firing pin Safety Upgrade. If a pistol is returned to you for service, please advise the owner that the slide assembly will be removed and returned to European American Armory Corp., 411 Hawk Street, Rockledge, Florida 32955. Upon receipt, European American Armory Corp. will replace with original firing pin with an upgraded firing pin.

Owners should also be advised to follow the instructions and warnings in the Owners' Manual and not disassemble a pistol beyond a field strip. Owners should be advised that any disassembly beyond a field strip should only be performed by a qualified gunsmith. In particular, the firing pin should never be removed by the owner. If the firing pin is removed, it must be re-installed correctly. If the firing pin is installed incorrectly in an upside down position, it may adversely affect the operation of the pistol and its safeties. If the owner's pistol is not functioning properly, the owner should discontinue using it and take it to a qualified gunsmith or European American Armory Corp. service center immediately.

Thank you for your attention to this Notice. Please call European American Armory Corp. at (800) 536-4442 if you have any questions regarding this Notice.